

Date: November 5, 2014

Subject: Burnham Commercial Apex Sensor Cap

In connection with our continuing efforts to improve our products, there has been a recent upgrade to Burnham Commercial's Apex 399, 500 and 800 Flue Temperature Sensor Caps. Burnham Commercial strongly recommends that during your next annual maintenance window the original sensor cap be replaced with the new and improved version.

Technical Discussion:

The Flue Temperature Sensor Cap was redesigned with a more durable fluoroelastomer material. The new material is black in color and is directly interchangeable with the original white silicon flue temperature sensor cap. Instructions for replacement are included in the Apex Flue Temperature Sensor Cap Replacement Kit, P/N 105318-01.



Original Flue Temperature Sensor Cap



New Flue Temperature

The new caps are available through either the wholesaler or the Sales Representative that sold you the Apex product. Please call them directly to arrange receipt of this upgraded part.